Owner Name and Address: Ezzies Wholesale Inc PO Box 1770 Malta MT 59538 Phone: (406) 654-2331

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0800855	Ezzies Wholesale Big Sandy	Ferry Star Route	Big Sandy	59520	(406) 378-2101

TankID/Alt TankID Status	·	talled e/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 12 Currently in Use	1843 6/1/199	-	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	ABC • EF GH I J K L B D E F GH I • K L	Yes Yes Yes Yes
2 / 10 Currently in Use	1842 5/18/19		Diesel 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	(ABC • EF GH () (K L) (B	Yes Yes Yes Yes
3 / 13 Currently in Use	1844 6/1/19		Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	(ABC • EFGH) J (K L) (B D E F G H) • (K L)	Yes Yes Yes Yes
4 / 14 Currently in Use	1845 6/1/19	-	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	B DEFGHIOKU	Yes Yes Yes Yes
11 / 09 Currently in Use	1841 5/18/19		Diesel 2,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	(ABC • EFGHIJKL B DEFGHI• KL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 1 of 20

Owner Name and Address: Nepil Bros Partnership 217 South Strevell Miles City MT 59301 Phone: (406) 232-3839

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0805363	Nepil Bros Partnership	HC 77 Box 809	Big Sandy	59520	

	Гад ımbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 1 Temporarily Out of Use	1748	7/1/1994 12 / No	Gasoline 3,000	STI-P3 None	Bare Steel Cathodically Protected	U.S. Suction	8 D • F G H 1 J K L	Yes Yes Yes Yes
4 / 04 1 Temporarily Out of Use	1749	7/1/1994 12 / No	Diesel 7,000	STI-P3 None	Bare Steel Cathodically Protected	U.S. Suction	ABCD®F@H1J&L B D®F@H1J&L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006

Owner Name and Address: Mountain View Coop 2200 Old Havre Highway Lincoln MT 59639 Phone: (406) 453-5900

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614150	Mountain View Coop Big Sandy	79211 US Highway 87	Big Sandy	59520	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently In Use	4965	1/31/2005 01 / Ye	Gasoline 5,000	Concrete None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGHIJKD B 0EF0HIJKL	No Yes Yes Yes
2 / S2 Currently In Use	4966	1/31/2005 01 / Ye	Diesel 5,000	Concrete None	Flexible Plastic Double-Walled	Pressurized	B	No Yes Yes Yes
3 / S3 Currently In Use	4967	/ Ye	Unknown 1	Concrete None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGHIJK● B DEF●HIJKL	No Yes Yes Yes
4 / S4 Currently In Use	4968	/ Ye	Unknown 1	Concrete None	Flexible Plastic Double-Walled	Not Listed	ABCDEFGHIJKD B DEFOHIJKL	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 20

Owner Name and Address: Schuler Lands Inc PO Box 367 Dutton MT 59433 Phone: (406) 476-3255

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0803976	Schuler Lands Inc East Farm	1700 Dent Bridge Road	Carter	59420	(406) 734-5404

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	4133 4	4/22/1982 24 / No	Gasoline 9,000	Fiberglass Reinforced Plastic None	No Piping None	Pressurized	(ABC⊕EFGH)J&L (B DEFGH)J&L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 4 of 20

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0809076	Malmstrom AFB J 3	US Highway 87	Carter	59420	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	157	8/1/1991 14 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	8 DEF®HIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 5 of 20

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0809078	Malmstrom AFB J 5	US Highway 87	Carter	59420	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	159	8/1/1991 14 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

Report Generation Date: 7/3/2006 Page 6 of 20

Owner Name and Address: Burlington Northern Santa Fe 920 South East Quincy Topeka KS 66612 Phone: (785) 435-2386

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
6015031	Carter BNSF Lease Property	3rd St and Railroad Tracks	Carter	59420	(785) 435-2386	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Temporarily Out of Us	-	1/1/1921 85 / Ye	Gasoline 1,100	Unknown None	Unknown None	Not Listed	ABCDEFGHIJK• B DEFGHIJK•	No No No No
2 / 02 Temporarily Out of Us		1/1/1921 85 / Ye	Diesel 1,100	Unknown None	Unknown None	Not Listed	(ABCDEFGH)JK• B DEFGH)JK•	No No No No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 7 of 20

Owner Name and Address: Mountain View Coop 2200 Old Havre Highway Lincoln MT 59639 Phone: (406) 453-5900

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0800005	Mountain View Coop Fort Benton	1820 Saint Charles St	Fort Benton	59442	(406) 622-2512

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 06 Currently in Use	1021	12/11/1976 29 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC0EFGHIJKL 0 0EFGHIJKL</pre>	Yes Yes Yes Yes
6 / 15 Currently in Use	1025	12/1/1991 14 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC●EFGHIJ® L ● ●EFGHIJ® L	Yes Yes Yes Yes
7 / 13 Currently in Use	1023	12/1/1991 14 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC ● EFGH1JKL ● OEFGH1JKL	Yes Yes Yes Yes
8 / 14 Currently in Use	1024	12/1/1991 14 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC●EFGHIJ®L ● ●EFGHIJ®L	Yes Yes Yes Yes
10 / 12 Currently in Use	1022	12/1/1991 14 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
16 / 16 Currently In Use	4628	3/28/2002 04 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC●EFGHIJ® L B DEF●HIJ® L	Yes Yes Yes Yes
17 / 17 Currently In Use	4629	3/28/2002 04 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H J K L B D E F • H J K L	Yes Yes Yes Yes
18 / 18 Currently In Use	4630	3/28/2002 04 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

19 / 19 Currently In Use	4631 3/28/2002 04 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEF GH 1 J K L	Yes Yes Yes Yes
20 / 20	4632 3/28/2002	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	(ABCOEFGH)J&U	Yes
Currently In Use	04 / No	30,000	None	Double-Walled		B (DEFOH)J&U	Yes Yes Yes
21 / 21	4633 3/28/2002	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	ABC • E F G H 1 J K L	Yes
Currently In Use	04 / No	30,000	None	Double-Walled		B D E F • H 1 J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006

Owner Name and Address: Riverside Business Inc 5809 Gooch Hill Rd Bozeman MT 59718 Phone: (406) 586-3531

Sys Fac I Loca	cation Name	Location Street Address	Location City	Zip	Location Phone
0800093 Joyce		1221 Main St	Fort Benton	59442	(406) 622-3381

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently in Use	4134 6/1/1999 07 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes
5 / 05	4135 6/1/1999	Gasoline	STI-P3	Flexible Plastic	Pressurized	ABCOEFGHUJKL	Yes
Currently in Use	07 / No	12,000	None	Double-Walled		B DEFOHUJKL	Yes Yes Yes
6 / 06	4136 6/1/1999	Gasoline	STI-P3	Flexible Plastic	Pressurized	ABCOEFGHUJKL	Yes
Currently in Use	07 / No	12,000	None	Double-Walled		B DEFOHUJKL	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

Report Generation Date: 7/3/2006 Page 10 of 20

Owner Name and Address: Chouteau County PO Box 459 Fort Benton MT 59442 Phone: (406) 622-3631

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0805930	County Courthouse & Jail	1215 Washington St	Fort Benton	59442	(406) 622-3631

TankID/Alt TankID Status		Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4118 6/	1/1988 18 / No	Diesel 550	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	U.S. Suction	<pre>B D E F O H 1 J K L</pre>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 11 of 20

Owner Name and Address: Perry Joyce PO Box 66 Geraldine MT 59446 Phone: (406) 737-4561

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613981	Joyce Fuel & Feeds Fort Benton	2118 Saint Charles St	Fort Benton	59442	(406) 622-3363

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4210	7/27/2000 05 / No	Gasoline 3,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC●EF®HIJKL B ●EF●HIJKL	Yes Yes Yes Yes
2 / 02 Currently In Use	4211	7/27/2000 05 / No	Gasoline 3,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	$\begin{array}{c} \textbf{B} \bullet \textbf{E} \textbf{E} \textbf{B} \textbf{I} \textbf{J} \textbf{K} \textbf{\Gamma} \\ \hline \end{array}$	Yes Yes Yes Yes
3 / 03 Currently In Use	4212	7/27/2000 05 / No	Diesel 3,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC ● EFGH1J&L B ●EF●H1J&L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 12 of 20

Owner Name and Address: Breen Oil KB Leasing PO Box 10 Choteau MT 59422 Phone: (406) 466-2575

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614147	Breen Oil Card Lock S	515 S Main St	Fort Benton	59442	(406) 466-2575

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently In Use	4950	1/14/2005 01 / Ye	Gasoline 6,000	Concrete None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJEL B DEFOHIJEL	No Yes Yes Yes
2 / S2 Currently In Use	4951	1/14/2005 01 / Ye	Gasoline 3,000	Concrete None	Flexible Plastic Double-Walled	Pressurized	B DEF@HIJ&L	No Yes Yes Yes
3 / S3 Currently In Use	4952	1/14/2005 01 / Ye	Diesel 3,000	Concrete None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJOL B DEFOHIJOL	No Yes Yes Yes
4 / S4 Currently In Use	4953	1/14/2005 01 / Ye	Diesel 5,000	Concrete None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJOL) B DEFOHIJOL	No Yes Yes Yes
5 / S5 Currently In Use	4954	1/14/2005 01 / Ye	Diesel 4,000	Concrete None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJOL) B (DEFOHIJOL)	No Yes Yes Yes
6 / S6 Currently In Use	4955	1/14/2005 01 / Ye	Diesel 3,000	Concrete None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJOL) B DEFOHIJOL	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 13 of 20

Owner Name and Address: Central Montana Coop PO Box 330 Geraldine MT 59446 Phone: (406) 737-4480

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
0806615	Central Montana Coop Geraldine	MT Highway 80	Geraldine	59446	(406) 737-4480	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently in Use	864	4/29/1974 32 / Ye	Gasoline 2,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	<pre>AB • DE F G H 1 J K L • • E F G H 1 J K L</pre>	Yes Yes Yes Yes
2 / S2 Currently in Use	865	4/29/1974 32 / Ye	Gasoline 2,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	AB • DE F G H 1 J K L • • E F G H 1 J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 14 of 20

Owner Name and Address: Richard L Schott 277 Broadway Ave W PO Box 26 Highwood MT 59450 Phone: (406) 733-5251

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
0812320	Highwood Service Center UST	277 Broadway Ave W	Highwood	59450	(406) 733-5251	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 03 Currently in Use	3112	9/1/1991 14 / No	Gasoline 1,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	ABCD®FGHIJKL B DEFGHI®KL	Yes Yes Yes Yes
2 / 04 Currently in Use	3113	9/1/1991 14 / No	Diesel 1,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	(ABCD®FGH)JKL B DEFGH)•KL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 15 of 20

Owner Name and Address: Garvey C Wood 203 Main St PO Box 207 Loma MT 59460 Phone: (406) 739-4224

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0801445	Midway Mercantile	204 Broadway	Loma	59460	(406) 739-4225

TankID/Alt TankID Status Tag Numb		Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 03 3957 Temporarily Out of Use	12/30/1986 19 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCDEFGHOJKL) (DEFGHIJKL)	Yes Yes Yes Yes
2 / 04 3958 Temporarily Out of Use	12/30/1986 19 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCDEFGHOJKL • • EFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 16 of 20

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
0809077	Malmstrom AFB J 4	US Highway 87	Rural Location	NZ008		

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02	158 8/1/1991	Diesel	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	U.S. Suction	ABCDEF.H.J.K.L	Yes
Currently in Use	14 / No	4,000	Double-Walled	Double-Walled		B DEF.H.J.K.L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 17 of 20

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0809079	Malmstrom AFB J 6	US Highway 87	Rural Location	NZ008	<u> </u>

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	160	5/21/1989 17 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	(A) B) C) DE F (A) H (1) (B) C (B) D) E F (A) H (1) (B) C	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 18 of 20

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0809080	Malmstrom AFB J 7	US Highway 87	Rural Location	NZ008	

TankID/Alt TankID Status	·	stalled je/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	161 8/1/1		Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	B DEF.H.I.K.L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging C	Inventory Control	■ Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 19 of 20

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
0809165	Malmstrom AFB R 23	Road 365	Rural Location	NZ008		<u>-</u>

TankID/Alt TankID Status	, , , , , , , , , , , , , , , , , , ,	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	162 5/3	/2/1966 40 / No	Diesel 11,000	Epoxy Coated Steel Impressed Current	Bare Steel Impressed Current	U.S. Suction	8 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 20 of 20